## PE-TH8010 Temperature Humidity Meter With Dew point





**Key Features:**
A 4-parameter measuring instrument designed to provide accurate humidity, dew point and temperature reading results. Equipped with dual display, displaying 2 reading results at the same time. It also have special functions such as data hold, MAX and MIN values, backlight and auto power off and operates on three AAA battrries only.

**PE-TH8010** **Temperature Humidity Metert With Dew Point**
The **PE-TH8010** is a humidity and temperature measuring instrument. It is normally used to measure the humidity and temperature in offices, storerooms, buildings and greenhouses.

## SPECIFICATIONS:

Measure Parameters: ℃, ℉, %RH(relative humidity), td(dew point temperature)

Range: -10 ～ +50℃, +14 ～ +122℉, 0 ～ +100%RH

Resolution：0.1℃, 0.1℉ ; 0.1%RH

Accuracy: ±1.0℃, ±1.8℉, ±3%RH（5～95%RH）

Sample Rate:1 time sec

Display: 4 digits LCD Display

Auto power off : About 20min

Dimension:121 x 60 x 30mm

Weight：180g

Power Supply: DC1.5V (AAA) x 3pcs

## Accessories include:

 Free 1.5V x3AAA batteries
Free protect cover
Free protective carrying case
Free Wrist Strap/String
User's Manual